
COUNTRY	Germany Approved	(Soviet Zone) For Release 2001/0	⊓ ∟ 3/06 : CIA-RDP®	200489R0€		68 25X1
TOPIC.	brieser 25X1X	Airfield				The state of the s
VALUATION_		PLACE C		X1A		
WATE OF CON	TENT		25X1A	4	The resemble to second the second to the sec	· ·
MIE OBTAIN		25X1	IA _DATE PREPARED_	24 50	ptember 1951	
EFERENCES			_DATE PREPARED_		beemer 1991	
		OSURES (NO. & TYPE)	1 - sketch	on ditto		
		OSONES (NO. & HPE)			AAA dagan daga	- TOT TOTAL LANGE (LA
Control of the Contro	ingen die der der der der der der der der der de	alle de la colificación de la color de	ACTIVISMO NIVER REPORTED VINITARIAN PROPERTY AND	ide distribution and describe an analysis of the second of	EMP TO E	
The state of the s	the state of the s	ridge en en viente de la verke en partie de de Balance (authority) a de verke de la verba de de la verba de de	DECER			
THE STATE OF THE S	ter (an east) de state Australia esperatorio est charac	CON . MINISTER COMPANY PROPERTY AND		and the Cast of th	J SO U B	
5X1X	tangunings, 407/9 year after sexus, and as grown adjusts to sexus adjusts			NOT CINCUL	N/F	
25X1A 1.	dates. F 300 labo The labo They wer railroad was emp brigade Accordin a prize	at, Bossweiler (Bauunion-Hast Corl. Bossweiler was rior to his arrivers from the Hapres arrived at equartered in the station. Thus, loyed at the fie varies from 10 to the bulletiof 5,000 DM east highest work pe	val he had diagdeburg area the field during a total of about the streng of 26 Hen dependent of the	rected that be employed ing the rep lings west but 2,700 G oth of a Ge	an additional at the field. orted period. of Brand erman workers	
25X1A 2. 25X1A 5X1A	1,700 me between (tar com Since the Level was seem necerunway na eastern i		as completed to of the runway bs were being or drainage for ather his to the constant to the constant was 900 met	is 50 meter filled with actilities and the adrainage ruction sure clears wide, a servide, a service a se	es. * The joint of Picosol ave been laid. ground water system did no erintendent, the ring of the tarted on	S
3。 25X1X	be kept be culties i	ricted areason bo de, thus forming the ecause the Torga n the terrain wh rack toward Lake	de target date u construction en laying the	for the co	ith the runway, mpletion would	•
4。 25X1X	A strip, 80, was b	eing concreted.	he concreted in the norther the course of	ed and grad but sown w	ed. ith grass.	25X1X
	CLAS	SSIFICATION PAODEN	CONTROL/US OF	FICIALS ONL	Y	ĺ
The same of the sa		CONLID	Partie Partie State of the Control o		the specified with reduce present section by the supplemental beautiful and section with	
		Document No. S No Change in Class. [Declassified Class. Changed To: Auth.: HR 70-2 Date: 3_0_AUG_1978_		RETURN LIBR	TO GIA ARY	

Approved For Release 2001/03/06 : CIA-RDP82-00457R008900320008-5

Approved For Release 2001/03/06 : CIA-RDP82-00457R008900320008-5



discernible. The taxiway had a width of 15 meters. Each of the 22 scheduled parking sites was 36 meters in diameter. **

- No work on lighting facilities or cable system was observed. The construction work on quartering facilities in Jagen 59/60 continued. A watchtower was to be erected in a wooded area in Jagen 70, not far from triangulation point 73.5 on the Brand-Frausnick road. The tower was to project slightly above the trees.
- The airfield was guarded by German sentries who wore red arm Brand-Lrausnick road was to be blocked after 25X1A
- 25X1A the field was inspected by a lieutenant-colonel from Werder. The officer who were blue-bordered golden coanlets arrived in passenger car Ho flying was 25X1B observed over the field during the period reported.
- 25X1A Conment. The runway was previously reported to be 60 neters wide. A width of about 50 meters is believed credible since runways of the same width are also under construction at other airfields. The runway is said to be 2,300 meters long. Since an average length of 250 to 350 meters is being concreted weekly, the entire runway will not be completed before the beginning of 25X1A 25X1A Comment. For schematic diagram of taxiway and aircraft hardstands, see Annex. The diameter of the hardstands may indicate that the field is scheduled to be occupied by twin-

1 Annex: One sketch on ditto.

engine aircraft.

25X1X

CONFIDENTIAL CELY